

Table of Contents

| | |
|---|----|
| 1. Background, aim and scope..... | 5 |
| 1.1. Background and scope | 5 |
| 1.2. Objective..... | 7 |
| 2. Assessment of the state of control of manufacturing processes..... | 9 |
| 2.1. GMP and ICH Q10 guidelines | 9 |
| 2.2. Statistical techniques applicable to the available data..... | 10 |
| 2.2.1. Background | 10 |
| 2.2.2. Definitions of Process under Control and Process Monitoring | 11 |
| 2.2.3. Statistical tools and their interpretation | 11 |
| 2.2.3.1. Determine if the variability of the process is constant over time..... | 11 |
| 2.2.3.2. To evaluate the ability of a process to obtain a conform product. Capability measurements..... | 12 |
| 2.2.3.3. Other capability measurements: machine capability (Cm, CmK), process performance (Pp, PpK) and coefficient of performance (Pr) | 15 |
| 2.2.3.4. Calculating the risk of non- compliance | 16 |
| 2.2.3.5. Process monitoring..... | 16 |
| 2.2.3.6. Sample size | 17 |
| 2.2.3.7. Monitoring trends..... | 18 |
| 2.2.3.8. Multivariate modeling | 20 |
| 2.2.3.9. Extracting knowledge from databases and data mining | 22 |
| 2.2.3.10. Neural Networks..... | 23 |
| 2.3. Applicable criteria and indicators to define the control strategy of pharmaceutical processes..... | 25 |
| 3. Evaluation of design and/or knowledge deficiencies on manufacturing processes. Proposal for improvement | 29 |
| 3.1. Implementation of ICH Q8 tools into the industrial manufacturing process | 29 |
| 3.1.1. Risk analysis and critical points..... | 29 |
| 3.1.2. Design of Experiments (DoE) | 32 |
| 3.2. Process validation..... | 33 |

| | | |
|--------|--|----|
| 3.3. | Proposed control strategy..... | 35 |
| 4. | Calculating the ROI of a QbD project..... | 35 |
| 4.1. | Need of economic return to ensure the viability of the project..... | 35 |
| 4.2. | Cost calculation, investment and ROI | 36 |
| 4.3. | Prioritizing tool to choose candidates for improvement projects. | 38 |
| 5. | Case Study..... | 41 |
| 5.1. | Description and background | 41 |
| 5.2. | Statistical evaluation of the state of control of the process | 43 |
| 5.2.1. | Summary of the quality attributes..... | 43 |
| 5.2.2. | Evaluation of process stability and trends observed | 43 |
| 5.2.3. | Estimating process capability and measuring the risk of non-conformity. | 45 |
| 5.2.4. | Conclusions about the observed state of control..... | 47 |
| 5.2.5. | Multivariable analysis and classification study of lots..... | 48 |
| 5.3. | Analysis of project profitability | 52 |
| 5.4. | Study of the process..... | 56 |
| 5.4.1. | Process mapping | 56 |
| 5.4.2. | Ishikawa or cause-effect diagram | 57 |
| 5.4.3. | Risk analysis..... | 58 |
| 5.4.4. | Experimental design..... | 63 |
| 5.4.5. | Experimental design in the mixing process | 63 |
| 5.4.6. | DoE in the compression process | 64 |
| 5.4.7. | DoE 1: Influence of raw material in the homogeneity of the mixture | 64 |
| 5.4.8. | DoE 2: influence of compression parameters on hardness and dissolution rate..... | 69 |
| 5.5. | Proposed specifications based on DoE studies | 72 |
| 5.6. | Proposed control strategy..... | 73 |
| 6. | Glossary..... | 75 |